

Franklin, John, Review of, May 11, 1950, 11/11/50  
 767 The ... 11/11/50  
 Hy. Doc. # MC. 07010/46 NARASIMHA et al

Vol. No. 212, 1950, 11/11/50

1/15

FIG. 1




FIG. 2




FIG.3




FIG. 4




FIG. 5




FIG. 6




FIG. 7





FIG. 8

STRAIN MEASURING POSITION  
( SECTION ON BROKEN LINE )



PROBABLE FRACTURING PORTION  
( POSITION OF MARK X ON SIDE WALL PORTION )



FIG. 9




FIG.10




FIG. 11




FIG.12





FIG.13




201110" E0654001

FIG. 14

STRAIN MEASURING POSITION

( SECTION ON BROKEN LINE )



PROBABLE FRACTURING PORTION

( POSITION OF MARK X ON SIDE WALL PORTION )

FIG.15

